

### R-416A Temp Chart

PSIG	R-416A	R-12	R-134A
0	-8	-22	-15
2	-3	-16	-10
4	2	-11	-5
6	6	-7	-1
8	10	-2	3
9	14	2	7
12	18	5	10
14	21	9	13
16	24	12	16
18	27	15	19
20	30	18	22
22	32	21	25
24	35	24	27
26	38	27	30
28	40	29	32
30	42	32	35
32	45	34	37
34	47	37	39
36	49	39	41
38	51	41	43
40	53	43	45
42	54	45	47
44	55	47	49
46	56	49	51
48	57	51	52
50	58	53	54
55	61	58	58
60	65	62	62
65	68	66	65
70	72	70	69
75	76	74	73
80	80	77	76
85	83	81	79
90	86	84	82
95	89	87	85
100	92	90	88
105	95	93	90
110	97	96	93
115	101	99	96
120	103	102	98
125	105	104	100
130	108	107	103
135	110	109	105
140	112	112	107
145	114	114	109

150	117	117	112
155	119	119	114
160	121	121	116
165	123	123	118
170	126	126	120
175	127	128	122
180	129	130	123
185	131	132	125
190	133	134	127
195	134	136	129
200	136	138	131